

FIG. 1



1/11

### FIG. 2A PRIOR ART



#### FIG. 2B PRIOR ART




FIG. 3A PRIOR ART




FIG. 3B PRIOR ART




FIG. 3C PRIOR ART






FIG. 3D PRIOR ART




#### FIG. 4A



# CONCENTRATION OF IMPURITY [cm<sup>-3</sup>]


◆ 4.00E+18
■ 8.00E+18
△ 1.17E+19
× 4.00E+19
\* 8.00E+19


FIG. 4B




# CONCENTRATION OF IMPURITY [cm<sup>-3</sup>]

1.60E+17
 2.50E+17
 3.64E+17
 5.50E+17
 7.00E+17






# FIG. 7 PRIOR ART








PRESSURE --





## FIG. 9A




FIG. 9B

